PSYCHROMETRY:

UNITS

DATA MAPPING

COMFORT OVERLAY

No Comfort Overlay

Reset | Options

PROCESS LINES

CHART METRICS

- [x] Dry-Bulb Temp.
- [x] Absolute Humidity
- [x] Relative Humidity
- [ ] Wet-Bulb Temp.
- [ ] Vapour Pressure
- [ ] Specific Volume
- [ ] Enthalpy

Default | None

Psychrometric Chart

INDICATOR:
Dry Bulb: 82.90 °F
Rel Humidity: 99.39%
Abs Humidity: 50.0 g/kg
Vap Pressure: 3.82211 kPa
Air Volume: 1.81988 m3/kg
Enthalpy: 156.12728 kJ/kg
Dew Point: 82.72 °F
Wet Bulb: 82.75 °F